

SUBJECT General: Materiel

Specific: MAINTENANCE MONTHLY UR REPORT - MARCH 1966.

IDEA 3101

ACTION REQUIRED REFERENCES

Approved For Release 2002/06/13 : CIA-RDP68B00724R000200310015-0

Copy 3

19 April 66

SECRET

1-1 Fuel Control, Part Number 522062PH, S/N 39664. Fuel leakage on top of fuel control Article 348. Total time on item, Unknown. Reason for failure, unknown, Negative.

1-2 Fuel Control, Part Number, 522062PH, S/N 23351, EGT and EPR decoy on several occasions above +16M. Article 348. Total time on item 122.8. Reason for failure, unknown. Negative.

1-3 DC Power Relay, Part Numbers, SP-A998, S/N AK63080. Battery Discharge light on intermittent once as high as 60% RPM Article 348. Total time on item 216.3. Reason for failure unknown. Negative.

1-4 DC Voltage regulator, Part Number, SP-CR2795E100B1, S/N 5145377. Battery discharge light on intermittent once as high as 60% RPM Article 348. Total time on item 61.2. Reason for failure, unknown. Negative.

1-5 Fuel Control, Part Number, 522062PH, S/N 23350. At +21, on third climb (after fuel system change over) RPM, EPR, and EGT fluctuated intermittently, with accompanying unusual noise. Article 348. Total time on item, unknown. Reason for failure unknown. Negative.

1-6 Brake, Part Number SP95-31237, S/N unknown. Right hand outboard brake leaks. Article 348. Total time on item unknown. Reason for failure unknown. Negative.

1-7 ARC 34, Part Number, F8988. S/N F10292. UHF went Inop, after T.O. and back on in let down. Article 348. Total time on item unknown. Reason for failure unknown. Negative.

1-8 ADF Power Supply, Part Number ARC 24630, S/N 1760. ADF inoperative. Article 348. Total time on item unknown. Reason for failure unknown. Negative.

1-9 Altimeter, Part Number, SP-Q-409-1, S/N AF57-20289. Altimeter sticks 300 to 400 feet during cruise climb, by tapping instrument it jumps approximately 400 feet. Article 348. Total time on item unknown. Reason for failure unknown. Negative.

1-10 Tachometer, Part Number, SP-8D143AAM, S/N K1488605. Moisture condensed on glass inside tachometer during third climb. Article 348. Total time on item unknown. Reason for failure unknown. Negative.

1-11 Hand Control Junction Box. Part Number, PE500-0132, S/N unknown. Hand Control junction box defective, Article 348. Total time on item unknown. Reason for failure unknown. Negative.

1-12 Drift Sight Knuckle Flange. Part Number, PE-152-0040, S/N Unknown. Drift sight does not shift completely from 4 to 1 power article 348. Total time on item unknown. Reason for failure unknown. Negative.

Approved For Release 2002/06/13 : CIA-RDP68B00724R000200310015-0

SECRET